

## Tech Bulletin

### Knurled Face Washer - Tip-Up Mounting

#### Summary of Bulletin

Some sites have reported that over time Tip-Ups are moving relative to the mount which eventually may lead to tray miss tips, and the need to reset the tip up device location.

To address this concern Globe has changed the mounting hardware as noted below to include a Knurled Face Washer, designed to better grip the composite tip up mount and eliminate any movement between the Tip-Up device and the Mount.



**GCS P/N:** 03-80-1380

**Description:** Knurled Face Washer

**QTY:** 3 washers required per Tip-Up

**Additional Notes:**

Orientation of Knurled Face as illustrated

Torque bolts to 15ft-lbs

